

AUGUST, 2008

Scott Home Inspection, LLC



George Scott, *Owner-Inspector*

Contact Info:

970-532-2424

720-979-4960

george@scotthomeinspection.com

Visit our website!

www.scotthomeinspection.com

Resources On-Line:

- [Services](#)
- [Sample Report](#)
- [Inspection Fees](#)
- [Schedule Availability](#)

Home-Tips On-Line:


[Five quick-tips to quickly recognize serious Structural problems](#)

[Radon - the 6 most frequently asked questions](#)

[Sump Pumps - Tips and Troubles](#)

Inspection Picture of the Month:

Oh where, oh where did all the insulation go: The owner of this new home was complaining that the home was very hot in winter and hard to heat in winter.



Investigation with an infra-red camera showed that the insulation along all of the upper attic knee walls was completely missing. With no insulation in these areas, all along the upper section of the home, the heat gain in summer, and heat loss in winter was tremendous.



New home inspections and 1-year warranty inspections can help to find areas like this, where a lack of quality control results in direct comfort issues with the occupants.