



# Inspection Connection

*e-Newsletter from Scott Home Inspection*

OCTOBER, 2010

Scott Home Inspection, LLC



George Scott, *Owner-Inspector*

## Contact Info:

970-532-2424

720-979-4960

[george@scotthomeinspection.com](mailto:george@scotthomeinspection.com)

Visit our website!

[www.scotthomeinspection.com](http://www.scotthomeinspection.com)

## Resources On-Line:

- [Services](#)
- [Sample Report](#)
- [Inspection Fees](#)
- [Schedule Availability](#)

## Home-Tips On-Line:

[View all past Inspection Connection Newsletters](#)

[Five quick-tips to quickly recognize serious Structural problems](#)

[Radon - the 6 most frequently asked questions](#)


[Sump Pumps - Tips and Troubles](#)

## Inspection Picture of the Month:

**Creative Dryer Venting:** This was one of the most creative dryer venting methods I have seen in a long while.



This is one of those items checked during a home inspection that is often over-looked. The length of run of a dryer vent, the type of material used, and the presence of an external damper are all important parts of ensuring the dryer is properly venting.



Everyone now and then we get to have some fun as inspectors, and finding something like this makes our day. It's the little things... But, ensuring proper dryer venting is just one more aspect of a thorough home inspection.